


1998 Minn Kota Riptide 55S



Wiring Diagram




Diagram # Product Info

- | | |
|----|---|
| 1 | <u>Minn Kota Trolling Motor Part Not Available</u> |
| 2 | <u>THRUST DISC - METAL - 303-042</u> |
| 3 | <u>BEARING - SPHERICAL - 144-021</u> |
| 4 | <u>Minn Kota Trolling Motor Part Not Available</u> |
| 5 | <u>BALL - STEEL 116-025</u> |
| 6 | <u>ARM ASSY 12V 4" - 2-100-094</u> |
| 7 | <u>RETAINING RING - 788-040</u> |
| 8 | <u>WASHER - STEEL THRUST - 990-051</u> |
| 9 | <u>WASHER - NYLATRON - 990-052</u> |
| 10 | <u>O-RING - 701-043</u> |
| 11 | <u>Minn Kota Trolling Motor Part Not Available</u> |
| 12 | <u>SCREW - SELF-THREAD 10-32X2.25 - 830-027</u> |
| 13 | <u>BRUSH PLATE ASSY, 4" - 409402</u> |
| 14 | <u>SPRING - TORSION - 975-041</u> |
| 15 | <u>Minn Kota Trolling Motor Part Not Available</u> |
| 16 | <u>SPACER - BRUSHPLATE - 973-025</u> |
| 17 | <u>BEARING - FLANGE - 144-017</u> |
| 18 | <u>Minn Kota Trolling Motor Part Not Available</u> |
| 19 | <u>SEAL - 880-025</u> |
| 20 | <u>O-RING - 701-009</u> |
| 21 | <u>THRU BOLT 12-24 X10.31 - 830-094</u> |
| 22 | <u>PIN-DRIVE (95-4HP'S) (SS) - 2092600</u> |
| 23 | <u>Minn Kota Weedless Wedge Propeller 2331120 / MKP-8 / 1378129 / 1865007</u> |
| 24 | <u>LOCKWASHER-PROP (LARGE) - 2091700</u> |
| 25 | <u>NUT-PROP (LARGE) - 2093100</u> |
| 26 | <u>Minn Kota Trolling Motor Part Not Available</u> |
| 27 | <u>Minn Kota Trolling Motor Part Not Available</u> |
| 28 | <u>TUBE (COMPOSITE) 36 - 2032052</u> |

29	<u>Minn Kota Trolling Motor Part Not Available</u>
30	<u>SCREW-CLAMP/WASHER KIT - 2881380</u>
31	<u>WASHER-CLAMP SCREW(1.5 OD - 2331700</u>
32	<u>Minn Kota Trolling Motor Part Not Available</u>
33	<u>Minn Kota Trolling Motor Part Not Available</u>
34	<u>Minn Kota Trolling Motor Part Not Available</u>
35	<u>Minn Kota Trolling Motor Part Not Available</u>
36	<u>Minn Kota Trolling Motor Part Not Available</u>
37	<u>E-RING 3/8 DIA. SHAFT* - 2263011</u>
38	<u>Minn Kota Trolling Motor Part Not Available</u>
39	<u>Minn Kota Trolling Motor Part Not Available</u>
40	<u>Minn Kota Trolling Motor Part Not Available</u>
41	<u>Minn Kota Trolling Motor Part Not Available</u>
42	<u>Minn Kota Trolling Motor Part Not Available</u>
43	<u>Minn Kota Trolling Motor Part Not Available</u>
44	<u>PIN-HINGE* - 2010511</u>
45	<u>BUSHING-HINGE - 2037301</u>
46	<u>TENSION BLOCK-"SNAP IN" - 2062800</u>
47	<u>COLLAR-DEPTH (W/O INSERT) - 2031520</u>
48	<u>SCREW-COLLAR/NEW KNOB(SS) - 2011366</u>
49	<u>LEADWIRE (10 GA) MAX/AT HAND - 2090650</u>
50	<u>CONNECT'GROUND WIRE-FUSED - 2060310</u>
51	<u>Minn Kota Trolling Motor Part Not Available</u>
52	<u>CONTROL BOX/COLLAR KIT - 2772596</u>
53	<u>COVER-CONTROL BOX - 2300219</u>
54	<u>DECAL-COVER (GENERIC) - 2345601</u>
55	<u>CONTROL BRD/HANDLE ASSY-MAX/HC- 12V - 2774002</u>
56	<u>SHRINK TUBE-3/8 OD X 1-1/ - 2305400</u>
57	<u>Minn Kota Trolling Motor Part Not Available</u>
58	<u>CONTROL BOX/COLLAR KIT - 2772596</u>

59	<u>Minn Kota Trolling Motor Part Not Available</u>
60	<u>HANDLE ASSY W/O U-JOINT - 2990914</u>
61	<u>HANDLE-BEARING-TILLER - 2060000</u>
62	<u>SPRING-DETENT(OFF) (SS) - 2302742</u>
63	<u>HANDLE (TOP HALF)MAXIMIZE - 2060411</u>
64	<u>HANDLE (LOWER HALF) - 2060415</u>
65	<u>BEARING-HANDLE PIVOT - 2060005</u>
66	<u>Minn Kota Trolling Motor Part Not Available</u>
67	<u>SPRING-DETENT(HANDLE-TILT - 2302743</u>
68	<u>SPRING-RELEASE BUTTON (SS - 2302745</u>
69	<u>RELEASE BUTTON-HANDLE - 2303720</u>
70	<u>SPRING-CAM(ZNC PLTD STEEL - 2302741</u>
71	<u>ACTUATOR-CAM - 2302850</u>
72	<u>SPRING-(ACTUATOR) - 2302740</u>
73	<u>Minn Kota Trolling Motor Part Not Available</u>
74	<u>ACTUATOR-FWD/REV - 2302851</u>
75	<u>WASHER-INSUL.(TRANSF.BAR) - 2301710</u>
76	<u>SCREW-8-18 X 5/8 THD* (SS - 2372100</u>
77	<u>SCREW-8-18 X 1/2 (SS)* - 2301310</u>
78	<u>CONNECTOR CABLE-(12") - 2340610</u>
79	<u>TERMINAL-SPADE, 10 GA - 2880704</u>
80	<u>Minn Kota Trolling Motor Part Not Available</u>
81	<u>BRUSH PLATE ASSY, 4" - 409402</u>
82	<u>BRUSH PLATE ASSY, 4" - 409402</u>
83	<u>Minn Kota Trolling Motor Part Not Available</u>
84	<u>Minn Kota Trolling Motor Part Not Available</u>